



maintenance management order

SUBJECT: Dual Pass Rough Cull (DPRC) Maintenance
Criteria Amendment to MMO-006-01

DATE: October 26, 2001

NO: MMO-096-01

TO: All Maintenance Capable Offices

FILE CODE: J9

dcle:mm01091aa

This bulletin amends MMO-006-01 to clarify the use of blown air (i.e., compressed air, vacuum exhaust, etc.) and vacuuming on the Dual Pass Rough Cull (RCULL). Effective with the release of this bulletin, the use of blown air in the routine servicing of this equipment is eliminated.

As an alternative to blown air, appropriate methods utilizing a HEPA filtered vacuum and brushing must be considered and implemented.

A new item, "open equipment and inspect dust conditions", must be added to the checklist to allow technicians/mechanics to determine the requirement for dust removal. If this inspection identifies suspect or unusual dust or debris, a supervisor or manager must be consulted prior to proceeding with any further action on the equipment.

Direct any questions or comments concerning this bulletin to the HelpDesk, Maintenance Technical Support Center, P.O. Box 1600, Norman OK 73070-1600; telephone FTS 2000 (405) 573-2123 or toll free (800) 366-4123.

Rex M. Gallaher
Manager
Maintenance Technical Support Center
Maintenance Policies and Programs