

MAINTENANCE TECHNICAL SUPPORT CENTER  
HEADQUARTERS MAINTENANCE OPERATIONS  
UNITED STATES POSTAL SERVICE



# Maintenance Management Order

**SUBJECT:** Bar Code Sorter & Induction Maintenance  
Criteria Amendment

**DATE:** October 29, 2001

**TO:** All Maintenance Capable Offices

**PUB NO:** MMO-126-01  
**FILE CODE:** Y  
**FILE ID:** mm01121  
**REV LEVEL:** aa

This bulletin amends the Bar Code Sorter & Induction Maintenance MMOs to clarify the use of blown air (i.e., compressed air, vacuum exhaust, etc.) and vacuuming on the Bar Code Sorter & Induction equipment. Effective with the release of this bulletin, the use of blown air in the routine servicing of this equipment is eliminated.

As an alternative to blown air, appropriate methods utilizing a HEPA filtered vacuum and brushing must be considered and implemented.

A new item, "open equipment and inspect dust conditions", must be added to the checklist to allow technicians/mechanics to determine the requirement for dust removal. If this inspection identifies suspect or unusual dust or debris, a supervisor or manager must be consulted prior to proceeding with any further action on the equipment.

Bulletin Number	Equipment	Acronym
MMO-038-01	Parcel Induction Stations	IDUCT
MMO-058-98	Belt Driven Sack Induction Stations (BDSIS)	IDUCT
MMO-058-99	Package Bar Code Sorter System (PBCSS) Secondary	BCS

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at **MTSC>HELPDESK>Create/Update Tickets** or call (800) 366-4123.

Rex M. Gallaher  
Manager  
Maintenance Technical Support Center  
HQ Maintenance Operations